


# ELECTRICAL SAFETY RECALL

## DC Solar Isolator

**"PVPower" branded XPDCISO1000V32A DC Isolator**



**PVPower  
brand mark**

**"PVPower" branded DC Isolator**, part number XPDCISO1000V32A.

Sold through electrical wholesalers or direct to solar contractors/installers between August 2012 to August 2013.

**DEFECT:** Product internal fault, where a high resistant connection may form

**HAZARD: RISK OF FIRE**

There is a risk that the DC isolator may overheat and, in some cases, cause fire.

**WHAT TO DO:**

**Electrical Contractors/Installers/Consumers**

Shut down the PV system. The DC Isolators are required to be replaced.

For a replacement program contact DKSH by phoning 1800 006 137 (during business hours), visiting <http://www.dksh.com.au/recall> or emailing [recall.au@dksh.com](mailto:recall.au@dksh.com).

**Wholesalers/Resellers**

Cease supplying PV Power DC Isolators and arrange returns by contacting 1800 006 137 or emailing [recall.au@dksh.com](mailto:recall.au@dksh.com). Visit <http://www.dksh.com.au/recall> for further details.

**For further information**

Please direct all calls and any queries concerning this recall to DKSH by phoning 1800 006 137 (during business hours), emailing [recall.au@dksh.com](mailto:recall.au@dksh.com) or visiting <http://www.dksh.com.au/recall>.

See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian product recall information