


# ELECTRICAL SAFETY RECALL

## TOSHIBA PC Power Cord

### AC Power Cord, model: LS-15

Sold with Toshiba PCs between Sept 2010 - Jun 2012



LS-15  
Moulded  
Marking

### IDENTIFICATION:

Some Toshiba notebook computers sold in Australia and New Zealand between September 2010 and June 2012 were shipped with “LS-15” branded AC power cords. The location of the “LS-15” marking is on the portion of the cord that plugs into the AC Adaptor, as shown in the red box in the above images.

Note: **not all** Toshiba PCs were sold with the affected AC power cord.

### HAZARD:

Some affected “LS-15” AC power cords may overheat and burn.

### ACTION REQUIRED:

1. Stop using your power cord immediately and unplug from the socket.
2. Visit the Toshiba website, <http://www.mytoshiba.com.au/support/item/853> to check if your power cord is affected (you will need your PC's Model and Serial Number.)
3. If affected you will be asked to register to receive a replacement AC power cord

For further information contact Toshiba (Australia) Pty Ltd  
13 30 70

See [www.recalls.gov.au](http://www.recalls.gov.au) for Australian product recall information