
ELECTRICAL SAFETY RECALL

Trinidad Ceiling Fan with LED Light

IDENTIFICATION (Located on the fan motor housing):

Mercator – Model no. FC428133BK, FC428133WH, FC428133WW



WHERE SOLD: These items were sold through Lighting Retail showrooms and Electrical Wholesaler outlets nationally.

DEFECT: When the diffuser (lamp cover) is removed from the fan access to live parts is possible if the ceiling fan light is turned on.

HAZARD: Risk of electric shock.

ACTION REQUIRED: DO NOT REMOVE the lamp cover. There is no need to remove the fan from ceiling. Consumers should register their product with the Mercator warranty department who will arrange for the installation of a safety cover by a qualified electrician at no cost to the consumer.

For further information

Please direct all calls and any queries concerning this recall to the Mercator Pty Ltd – Warranties department – 1300552255 or warranty.administrator@mercator.com.au

See <u>www.recalls.gov.au</u> for Australian product recall information